


DEPARTMENT OF INTELLIGENCE

REPORT ON THE EFFECTS AND RESULTS OF THE BOMBING OF GERMANY BY  
THE 8<sup>TH</sup> BRIGADE AND INDEPENDENT FORCE, ROYAL AIR FORCE:  
MISCELLANEOUS PHOTOGRAPHS

Due to the poor quality of the original this is a facsimile copy produced by the JSCSC Library.

No. 8.B.85



OPPAU.

Damage to gas pipes at gasometre No. 505.  
22<sup>nd</sup> May, 1918.

No. 8.B.37.



ROMBAS.

The interior of a workman's house pierced by a French bomb in 1917.

No. 8.B.36.



HAGONDANGE.

Crater of a 230 lb. bombs.

No. 8.B.169.



METZ SABLONS.

Barracks.

No. 8.B.78.



PIRMASENS.

Effect of a 112 lb. bomb.

No. 8.B.56.



THIONVILLE.

Destroyed military telephone centre.

No. 8.B.22



KAISERSLAUTERN.

The Southern wing of the Factory destroyed by 1650 lb. bombs.

No. 8.B.119.



OPPAU WORKS.

Crater of a 230 lb. bomb.

No. 8.B.61.



BONN.

Showing penetration effect of a 112 lb. bomb.

No. 8.B.82.



PIRMASENS.

Destroyed house.

No. 8.B.195.



METZ SABLONS.

Damage to dwelling.

No. 8.B.198.



METZ.

Damage to outhouses of barracks.


No. 8.B.93.



TREVES.

Interior of the destroyed Wing of the Museum.

No. 8.B.197



TREVES.

Damage done to a gasometre at TREVES Station by a French bomb.

No. 8.B.88.



TREVES.

Burnt out row of houses.



THONVILLE.

Portion of the N.C.O's quarters of the Barracks  
destroyed by a bomb.

No. 8.B.129.



TREVES.

General view of burning Convent.



THONVILLE.

Destroyed dwelling.

No. 8.B.192.



OPPAU WORKS.

Crater of a 112 lb. bomb.



TREVES.

The destroyed roof of the museum.

No. 8.B.128.



TREVES.

Damage to Toolshop at the AGNETEN BARRACKS.

No. 8.B.32.



TREVES.

Same as No. 8.B.128.

No. 8.B.130.



TREVES.

Damage to hot houses.

No. 8.B.239.



TREVES.

Top story of a Convent burnt out.

No. 8.B.147.



DUREN.

A blind bomb.

No. 8.B.369.



BONN.

Crater of 112 lb. bomb.